

# TABLE OF CONTENTS

## CHAPTER 1: INTRODUCTION

SAN JUAN RIVER STUDY AREA .....	1-1
---------------------------------	-----

## CHAPTER 2: HYDROLOGY

BACKGROUND .....	2-1
METHODS .....	2-1
RESULTS .....	2-1
Storm Influence .....	2-6

## CHAPTER 3. GEOMORPHOLOGY

METHODS .....	3-1
Channel Morphology - River Transects .....	3-1
Cobble Bar Characterization .....	3-2
Turbidity Monitoring .....	3-3
RESULTS .....	3-3
Channel Morphology - River Transects .....	3-3
Measurement of Change in Reach 1 Cross-Sections .....	3-7
Cobble Substrate Characterization .....	3-7
Topographic Changes in Cobble Bars .....	3-7
Characterization of Bed Material .....	3-14
Depth of Open Interstitial Space .....	3-14
Suspended Sediment Analysis .....	3-27
Sediment Sampling .....	3-27
Turbidity Monitoring .....	3-27

## CHAPTER 4. WATER QUALITY

METHODS .....	4-1
Water Temperature .....	4-1
Water Chemistry .....	4-1
RESULTS .....	4-1
Water Temperature .....	4-1
Water Chemistry .....	4-5

## CHAPTER 5. HABITAT STUDIES

HABITAT QUANTITY .....	5-1
HABITAT QUALITY .....	5-1

## APPENDIX A

# LIST OF TABLES

Table 2.1.	Summary of Navajo Dam release hydrograph characteristics since the beginning of the research period, 1992 to 1999. ....	2-2
Table 2.2.	Flow Statistics met in each year .....	2-3
Table 2.3.	Summary of flows for the research (1991-1998) and monitoring (1999) periods, San Juan River at Four Corners, New Mexico .....	2-4
Table 3.1.	San Juan River channel morphology monitoring cross-section locations by geomorphic reach. ....	3-1
Table 3.2.	Peak discharge and Volume at Bluff (1991 - 1999) .....	3-6
Table 3.3.	Summary of cobble bar change for bars at RM 173.7, 168.4 and 132. ....	3-9
Table 3.4.	Summary of percent cobble substrate, pre- and post-runoff, 1999 for Reach 3-6 transects. ....	3-16
Table 3.5.	Cobble size distribution for the four surveyed cobble bars. ....	3-18
Table 3.6.	Flow based Sediment Event Days and Turbidity based Sediment Days. ...	3-31
Table 4.1.	Water temperature monitoring locations and period of record .....	4-2
Table 4.2.	San Juan River water quality monitoring sites .....	4-3
Table 4.3.	San Juan River Monitoring Program water quality parameters .....	4-3
Table 4.4.	Water chemistry data for San Juan River at Archuleta Bridge .....	4-6
Table 4.5.	Water Chemistry data for Animas River at Farmington .....	4-7
Table 4.6.	Water Chemistry data for San Juan River at Farmington Bridge .....	4-8
Table 4.7.	Water chemistry data for La Plata River near Farmington .....	4-9
Table 4.8.	Water chemistry data for San Juan River at Shiprock Bridge .....	4-10
Table 4.9.	Water chemistry data for Mancos River near Four Corners .....	4-11
Table 4.10.	Water chemistry data for San Juan River at Four Corners Bridge .....	4-12
Table 4.11.	Water chemistry data for San Juan River at Montezuma Creek Bridge ....	4-13
Table 4.12.	Water chemistry data for San Juan River at Bluff Bridge .....	4-14
Table 4.13.	Water chemistry data for San Juan River at Mexican Hat Bridge .....	4-15
Table 5.1.	Seven general categories of habitat types on the San Juan River .....	5-2

# LIST OF FIGURES

Figure 1.1.	San Juan Basin Location Map Showing Geomorphic Reaches . . . . .	1-2
Figure 2.1.	1999 hydrographs for Anims River at Farmington, San Juan River at Archuleta and Four Corners. . . . .	2-3
Figure 2.2.	Hydrographs for the San Juan River at Four Corners for 1991 - 1994. . . . .	2-5
Figure 2.3.	Hydrographs for the San Juan River at Four Corners for 1995 - 1999. . . . .	2-5
Figure 3.2.	Minimum relative bed elevation for Reach 3-6 transects, 1992-1999 . . . . .	3-4
Figure 3.1.	Average relative bed elevation for Reach 3-6 transects, 1992-1999. . . . .	3-4
Figure 3.3.	Mean relative bed elevation for Reach 3-6 Transects, 1992-1999 . . . . .	3-5
Figure 3.4.	Minimum bed elevation averaged for Reach 3-6 Transects, 1992-1999 . . . . .	3-5
Figure 3.5.	Net change in Reach 3-6 Transects, 1992-1999 . . . . .	3-6
Figure 3.7.	Bed elevation averaged for both transects in Reach 1, 1993-1999 . . . . .	3-8
Figure 3.6.	Average relative bed elevation for Reach 1 transects, 1993-1999. . . . .	3-8
Figure 3.8.	Lake Powell water surface elevation, 1986-1999. . . . .	3-9
Figure 3.9.	Topography of cobble bar at RM 173.7, 1993-1999 . . . . .	3-10
Figure 3.10.	Topography of cobble bar at RM 168.4, 1993-1999. . . . .	3-11
Figure 3.11.	Topography of cobble bar at RM 132, 1995-1999. . . . .	3-12
Figure 3.12.	Topography of cobble bar at RM 131, 1997-1999 . . . . .	3-13
Figure 3.13.	Areas of scour and deposition pre- to post-runoff for the RM173.7 cobble bar . . . . .	3-15
Figure 3.14.	Area of scour and deposition pre- to post-runoff for the RM 168.4 cobble bar. . . . .	3-15
Figure 3.15.	Area of scour and deposition pre- to post-runoff for the RM 132 cobble bar. . . . .	3-16
Figure 3.16.	Scour and deposition composition at Reach 3-6 transects between pre- and post-runoff, 1999. . . . .	3-17
Figure 3.17.	Cobble percentage at each transect, 1992-1999. . . . .	3-17
Figure 3.18.	November 15, 1999 survey with embeddedness markers. . . . .	3-19
Figure 3.19.	November 16, 1999 survey with embeddedness markers. . . . .	3-19
Figure 3.20.	October 28, 1999 survey with embeddedness markers. . . . .	3-20
Figure 3.21.	October 28, 1999 survey with embeddedness markers. . . . .	3-20
Figure 3.22.	Frequency Distribution of Depth of Open Interstitial Space for Cobble Bar 173.7 expressed in cm. . . . .	3-21
Figure 3.23.	Frequency Distribution of Depth of Open Interstitial Space for Cobble Bar 173.7 expressed in d50 cobble size. . . . .	3-21

Figure 3.24.	Frequency Distribution of Depth of Open Interstitial Space for Cobble Bar 168.4 expressed in cm. ....	3-22
Figure 3.25.	Frequency Distribution of Depth of Open Interstitial Space for Cobble Bar 168.4 expressed in d50 cobble size. ....	3-22
Figure 3.26.	Frequency Distribution of Depth of Open Interstitial Space for Cobble Bar 132 (m-6) expressed in cm. ....	3-23
Figure 3.27.	Frequency Distribution of Depth of Open Interstitial Space for Cobble Bar 132 (M-6) expressed in d50 cobble size. ....	3-23
Figure 3.28.	Frequency Distribution of Depth of Open Interstitial Space for Cobble Bar 131 (M-4) expressed in cm. ....	3-24
Figure 3.29.	Frequency Distribution of Depth of Open Interstitial Space for Cobble Bar 131 (M-4) expressed in d50 cobble size. ....	3-24
Figure 3.30.	Area of Depth of Open Interstitial Space Exceedence for 173.7. ....	3-25
Figure 3.31.	Area of Depth of Open Interstitial Space Exceedence for 168.4. ....	3-25
Figure 3.32.	Area of Depth of Open Interstitial Space Exceedence for 132 (M-6). ....	3-26
Figure 3.33.	Area of Depth of Open Interstitial Space Exceedence for 131 (M-4). ....	3-26
Figure 3.34.	Results of 1999 Suspended Sediment Sampling ....	3-27
Figure 3.35.	Historical Sediment Concentration at Bluff ....	3-28
Figure 3.36.	Montezuma Creek Turbidity Data and Four Corners Gage Flow ....	3-29
Figure 3.37.	Shiprock Turbidity Data and Shiprock Gage Flow ....	3-29
Figure 3.38.	Montezuma Creek and Shiprock Turbidity versus Concentration. ....	3-32
Figure 4.1.	San Juan Basin Water Average Temperature Data ....	4-4
Figure 4.2.	Archuleta Maximum, Minimum and Average Water Temperatures ....	4-4
Figure 4.3.	Montezuma Creek Maximum, Minimum and Average Water Temperatures .	4-5
Figure 5.1.	The percent distribution of general habitats in the San Juan River during November-December 1998. ....	5-2
Figure 5.2.	The spatial distribution of habitats in the San Juan River, November - December 1998. Run habitats are not shown. ....	5-3
Figure 5.3.	The habitat diversity values for the San Juan River (Reaches 1-6) and the overall river-wide average for November 1998 compared to previous trips where flows were between 800-1,200 cfs. ....	5-4
Figure 5.4.	The surface area (above) and counts (below) of backwater habitats in the San Juan River between July 1991 and November 1998. Data are for each reach and RM 2 through 180. ....	5-5
Figure 5.5.	The surface area of backwaters (above) and counts (below) for three reaches in the San Juan River between July 1991 and November 1998. ....	5-6
Figure 5.6.	The depth of sediments (meters) in backwater habitats of the San Juan River. ....	5-7